



PK = 1000,00
Rze = 221,12

PK = 1054,48; Rze = 220,78
PPP = 1052,64; K/P = 1055,32
R = 2000,00
T = 1,94; B = 0,00

PK = 1177,24; Rze = 220,24
PPP = 1170,74; K/P = 1183,74
R = 1500,00
T = 6,58; B = 0,01

PK = 1239,09; Rze = 219,17
PPP = 1239,00; K/P = 1278,27
R = 1000,00
min: PK=1232,98; Rze=219,34
T = 19,19; B = 0,18

PK = 1330,62; Rze = 220,98
PPP = 1310,04; K/P = 1351,20
R = 1000,00
max: PK=1335,34; Rze=220,78
T = 20,58; B = 0,21

PK = 1405,00; Rze = 219,80
PPP = 1366,73; K/P = 1443,28
R = 3000,00
min: PK=1414,31; Rze=220,03
T = 38,28; B = 0,24

PK = 1550,00; Rze = 221,20
PPP = 1539,52; K/P = 1560,48
R = 2000,00
max: PK=1558,63; Rze=221,19
T = 10,48; B = 0,03

PK = 1635,00; Rze = 221,13
PPP = 1628,08; K/P = 1641,91
R = 2000,00
T = 6,91; B = 0,01

PK = 1832,77; Rze = 219,60
PPP = 1826,33; K/P = 1838,61
R = 2000,00
T = 5,84; B = 0,01

PK = 1885,14; Rze = 219,50
PPP = 1879,54; K/P = 1891,28
R = 2000,00
min: PK=1883,34; Rze=219,51
T = 5,87; B = 0,01

PK = 1935,80
Rze = 219,70